

Contents

Foreword	xv
Authors	xvi
Chapter 1 Introduction.....	1
1.1. Basic Principles of Extrusion	1
Historic Development of Extrusion	2
Chapter 2 Extruded Products.....	9
2.1Tin and Lead Extruded Products with a Deformation Temperature Range of 0 to 300°C	9
2.2Magnesium and Aluminum Extruded Products with a Working Temperature Range of 300 to 600°C	11
2.2.1 Magnesium Alloy Extruded Products	11
2.2.2 Aluminum Alloy Extruded Products	12
2.2.2.1 Transport Construction	15
2.2.2.2. Machine Manufacture, Electrical Machines, and Electrical Equipment	36
2.2.2.3 Architecture	40
Extruded Products from Materials with a Working Temperature Range of 600 to 1300 °C	49
2.3 Copper Alloy Extruded Products	49
2.4 Extruded Titanium Alloy Products	55
2.5 Extruded Products in Iron Alloys and Other Hot-Working Alloys	56
Chapter 3 Rod and Tube Extrusion Processes	59
3.1 Direct Extrusion	59
3.1.1 Direct Hot Extrusion without Lubrication and Shell (Aluminum Alloys)	61
3.1.1.1 Process Sequence of Direct Hot Extrusion without Lubrication or Shell	61
3.1.1.2 Variation in the Extrusion Load with Stem Movement in Direct Hot Extrusion without Lubrication or Shell	61
3.1.1.3 Material Flow in Direct Hot Extrusion	66
3.1.1.4 Calculation of the Axial Loads in Direct Hot Extrusion without Lubrication and Shell (Aluminum Alloys)	70
3.1.1.5 Thermal Changes in Direct Hot Extrusion of Aluminum	76
3.1.2 Direct Hot Extrusion without Lubrication and with a Shell (Copper Alloys)	81
3.1.2.1 Process Sequence for Direct Hot Extrusion without Lubrication and with a Shell.....	81
3.1.2.2 Variation in the Stem Load <i>over the Stem Displacement</i> in Direct Hot Extrusion without Lubrication and with a Shell	84
3.1.2.3 Material Flow in Direct Hot Extrusion without Lubrication and with a Shell.....	84
3.1.2.4 Calculation of the Axial Forces in Direct Hot Extrusion without Lubrication and with a Shell	84

3.1.2.5 Thermal Conditions in Direct Hot Extrusion without Lubrication and with a Shell	85
3.1.3 Direct Hot Extrusion with Lubrication and without a Shell (Steel)	87
3.1.3.1 Process Sequence in Direct Hot Extrusion with Lubrication and without a Shell	87
3.1.3.2 Variation in the Stem Load with Stem Displacement in Direct Hot Extrusion with Lubrication and without a Shell	88
3.1.3.3 Material Flow in Direct Hot Extrusion with Lubrication	88
3.1.3.4 Thermal Conditions in Direct Hot Extrusion with Lubrication	89
3.1.4 Direct Cold Extrusion with Lubrication and without a Shell	89
3.1.4.1 Process Sequence in Direct Cold Extrusion with Lubrication and without a Shell	89
3.1.4.2 Stresses, Axial Loads, and Temperature Increase	89
3.2 Indirect Extrusion.....	95
3.2.1 Hot Indirect Extrusion without Lubrication and without a Shell (e.g., Aluminum Alloys)	96
3.2.2 Hot Indirect Extrusion without Lubrication and with a Shell	98
3.2.3 Material Flow in Indirect Hot Extrusion.....	100
3.2.4 Axial Forces and Extrusion Exit Temperatures in the Indirect Hot Extrusion with an Initial Billet Temperature Equal to the Container Temperature (e.g., Aluminum Alloy Extrusion)	104
3.2.5 Axial Loads and Exit Temperatures in Indirect Hot Extrusion with an Initial Billet Temperature Higher than the Container Temperature (e.g., in the Extrusion of Copper Alloys)	108
3.2.6 Comparison of the Indirect Hot Extrusion Process with Direct Hot Extrusion	109
3.2.7 Indirect Cold Extrusion	110
3.2.7.1 Indirect Cold Extrusion with Lubrication and without a Shell	110
Hydrostatic Extrusion	114
3.3 Conventional Hydrostatic Extrusion	114
3.3.1 Process Principles	114
3.3.2 Process Sequence.....	116
3.3.3 Axial Loads in Hydrostatic Extrusion	117
3.3.4 Products	118
3.4 Thick Film Process	120
Special Processes	122
3.5 Conform Process	122
3.5.1 Process Principle	123
3.5.2 Process Variations of the Conform Process	124
3.5.2.1 Extrusion of Granules and Powder	124
3.5.2.2 Combination of Casting and Conform Extrusion	124
3.5.2.3 Fiber Cladding by Conform Extrusion	125
3.5.2.4 Cable Sheathing with the Conform Extrusion Process	125
3.6 Cable Sheathing	126
3.6.1 General	126
3.6.2 Principle of Cable Extrusion	126
3.6.3 Sheathing with Lead	126
3.6.3.1 Materials and Process	126
3.6.3.2 Cable Sheathing with Lead	127
3.6.4 Sheathing with Aluminum	128
3.6.4.1 Aluminum as a Cable Sheathing Material	128
3.6.4.2 General Process	128
3.6.4.3 Discontinuous Extrusion	129
3.6.4.4 Continuous Extrusion	129
3.7 Tube Extrusion Process.....	130
3.7.1 Direct Tube Extrusion	130

3.7.1.1 Direct Hot Tube Extrusion over a Fixed Mandrel	130
3.7.1.2 Direct Hot Tube Extrusion with a Moving Mandrel	131
3.7.1.3 Direct Hot Tube Extrusion with a Shell	132
3.7.1.4 Analysis of the Axial Forces in Direct Hot Tube Extrusion	133
3.7.2 Indirect Tube Extrusion	135
3.7.2.1 Indirect Tube Extrusion over a Stationary Mandrel	136
Chapter 4 Metallurgical Principles.....	141
4.1 Introduction	141
4.2 Structure.....	141
4.2.1 Lattice Structure Single Phase	141
4.2.2 Multiphase Structure—Equilibrium Diagrams	144
4.2.2.1 Binary Systems	144
4.2.2.2 Intermediate Phases	148
4.2.2.3 Multicomponent Systems	148
4.2.3 Diffusion, Precipitation, Nonequilibrium	148
4.2.4 Melting and Casting Processes	152
Casting and Cast Structure, Homogenizing of Aluminum Alloys	152
4.3 Development of the Continuous Cast Structure	152
4.3.1 Peripheral Shell and Peripheral Segregation	154
4.3.2 Cast Log Surface	154
4.3.3 Cast Grain and Cell Structure, Intermetallic Phases.....	156
4.3.4 Homogenizing.....	158
Casting and Cast Structure of Copper Alloys	159
4.4 Segregation and Gas Porosity	159
4.5 Cooling and Casting Defects	160
4.5.1 Cast Log Surface	160
4.5.2 Interior of the Cast Log	162
Deformation, Recovery, Recrystallization.....	162
4.6 Deformation of Pure Metals at Room Temperature	162
4.6.1 Dislocations	162
4.6.2 Single Crystals	163
4.6.3 Polycrystals	164
4.7 Deformation of Alloys at Room Temperature	167
4.8 Higher Temperatures with Pure Metals	169
4.8.1 Annealing of Pure Metals.....	169
4.8.2 Deformation of Pure Metals at High Temperatures.....	172
4.9 Alloys at Higher Temperatures	173
4.9.1 Annealing of Alloys	173
4.9.2 Deformation of Alloys at Higher Temperatures	174
4.10 Processes in Extrusion	174
4.11 Toughness, Fracture	177
4.11.1 Ductile Fracture	177
4.11.2 Brittle Fracture and Mixed Types	178
4.11.3 Fracture during Hot-Working	178
4.11.4 Defects in Extrusion	178
4.12 Solid-State Bonding	180
4.12.1 Bonding Processes	180
4.12.2 The Formation of Pressure Welds in Hollow Sections and during Billet-on-Billet Extrusion.....	180
4.12.3 Composite Extrusion	182
4.12.4 Powder Extrusion.....	183
4.12.5 Friction between the Extruded Material and the Tooling	184
4.13Extrudability of Metallic Materials	186

5.11.1 General	239
5.11.1.1 Copper, Bronze, and Brass—A Long History	239
5.11.1.2 Advantageous Physical and Chemical Properties	239
5.11.1.3 Importance of Extrusion in the Processing	240
5.12 The Groups of Extruded Copper Alloys—Their Important Properties and Applications	241
5.12.1 Alloy Groups	241
5.12.2 Tooling Temperatures in Extrusion	241
5.12.3 Structure.....	241
5.12.4 Typical Extruded Semifinished Products and Applications	241
5.13 Extrusion Properties of Copper Alloys	242
5.13.1 Extrudability of Different Materials	242
5.13.2 Temperature and Speed—Structure of the Extrusion	242
5.13.3 Extrusion to Finished or Close-to-Finished Dimensions	243
5.13.4 Lubrication	243
5.13.5 Extrusion with a Shell	243
5.13.6 Different Material Flow Behavior	244
5.13.6.1 Flow-Type C—Piping Defect.....	244
5.13.6.2 Flow-Type B—Shell Defect	244
5.13.6.3 Back End Defect	244
5.13.7 Discard Length	244
5.13.8 Direct Extrusion with Lubrication and without a Shell	244
5.13.9 Extrusion into Water or Air	245
5.14 Extrusion Processes and Suitable Equipment	245
5.14.1 Extrusion Presses for Brass Wire and Sections	245
5.14.2 Tube Extrusion	245
5.14.3 Drive	245
5.14.4 Die Changing	246
5.14.5 Discard Separation.....	246
5.15 Billet Production and Heating	^ 246
5.15.1 Continuous Casting and Homogenizing	246
5.15.2 Billet Length	246
5.15.3 Billet Processing	246
5.15.4 Billet Quality Control	246
5.15.5 Billet Heating	246
5.16 Copper Extrusion	247
5.16.1 General	247
5.16.1.1 The Different Grades of Copper, Their Properties and Applications	247
5.16.1.2 Hot Workability, Extrusion Temperature	247
5.16.2 Copper Tube	247
5.16.2.1 Application.....	247
5.16.2.2 Production Methods	248
5.16.2.3 Extrusion	248
5.16.2.4 Oxide on the Billet Surface, Shell and Blister Defect	248
5.16.3 Copper Rod and Section.....	249
5.16.3.1 Dimensions and Shape, Further Processing	249
5.16.3.2 Hollow Sections	249
5.16.4 Extrusion of Low-Alloy Copper Materials	250
5.16.4.1 The Materials, Properties, and Applications	250
5.16.4.2 Extrusion	251
5.16.4.3 Solution Treatment at the Press	251
5.16.5 Extrusion of Copper-Zinc Alloys (Brass and Tombac)	251
5.16.5.1 Binary Copper-Zinc Alloys	251
5.16.5.2 Copper-Zinc Alloys with Alloy Additions (Special Brasses)	256
5.16.6 Extrusion of Copper-Tin Alloys (Tin Bronzes)	257

Appendix: Additional Information for Chapter 4 Metallurgical Principles	189
• Additional Information 1: Miller's Indices to Describe a Space Lattice	189
• Additional Information 2: Representation of Textures in Pole Figures	191
• Additional Information 3: Temperature and Speed Dependence of the Flow Stress in Hot Working	191
Chapter 5 The Production of Extruded Semifinished Products from Metallic Materials.....	195
Extrusion of Materials with Working Temperatures between 0 and 300 °C	195
5.1 Extrusion of Semifinished Products in Tin Alloys	195
5.2 Extrusion of Semifinished Products in Lead Materials.....	197
5.3 Extrusion of Tin- and Lead-Base Soft Solders	199
5.4 Extrusion of Zinc Alloy Semifinished Products	202
Extrusion of Materials with Deformation Temperatures between 300 and 600 °C	203
5.5 Extrusion of Semifinished Products in Magnesium Alloys	203
Extrusion of Semifinished Products in Aluminum Alloys	207
5.6 General	207
5.7 Extrusion Behavior of Aluminum Alloys	208
5.7.1 Flow Stress.....	208
5.7.2 Flow Process	209
5.7.2.1 The Dead Metal Zone	209
5.7.2.2 In the Shape-Producing Aperture	210
5.7.3 Thermal Balance and Extrusion Speed.....	210
5.7.4 Section Surface and Surface Defects	212
5.7.4.1 Section Surface and the Peripheral Layer	212
5.7.4.2 Cast Structure and Anodizing Capability	213
5.7.4.3 Surface Roughness	214
5.7.4.4 Transverse Cracks and Peeling	217
5.7.5 Procedures to Control the Thermal Balance	217
5.7.5.1 Material	218
5.7.5.2 Billet Temperature	218
5.7.5.3 Heat Removal	218
5.7.5.4 Optimization of the Extrusion Parameters	220
5.7.6 Joining by Extrusion	221
5.7.6.1 Extrusion Welding	221
5.7.6.2 Longitudinal Welds in Hollow Sections	222
5.7.6.3 Transverse Welds	224
5.7.6.4 Testing of Extrusion Welds	225
5.7.6.5 Influence of the Extrusion Weld on the Surface Appearance	225
5.7.6.6 Suitability of the Material for Hollow Section Extrusion	226
Materials	226
5.8 Easily Extruded Alloys	229
5.8.1 Aluminum Alloys	229
5.8.2 Extruded Products	230
5.8.3 Extrusion and Materials Properties	231
5.9 Moderately Difficult Alloys	233
5.9.1 Aluminum Alloys	233
5.9.2 Extruded Products	235
5.9.3 Extrusion and Materials Properties	236
5.10 Difficult-to-Extrude Alloys	237
5.10.1 Aluminum Alloys	237
5.10.2 Extruded Products	238
5.10.3 Extrusion and Materials Properties	238
Extrusion of Materials with Deformation Temperatures of 600 to 1300 °C	239
5.11 Extrusion of Semifinished Products in Copper Alloys	239

5.16.6.1 The Different Alloys, Their Structures, Properties, and Applications	257
5.16.6.2 Casting of Copper-Tin Alloys	258
5.16.6.3 Extrusion of Copper-Tin Alloys	258
5.16.6.4 Flow Type and Shell Defects	258
5.16.6.5 Competition from Wire Casting	258
5.16.7Extrusion of Copper-Aluminum Alloys (Aluminum Bronzes)	258
5.16.7.1 The Different Alloys, Their Properties, and Applications	258
5.16.7.2 Binary Copper-Aluminum Alloys	259
5.16.7.3 Copper-Aluminum Alloys with Additions (Complex Aluminum-Bronzes)	260
5.16.8Extrusion of Copper-Nickel Alloys	260
5.16.8.1 Materials, Structure, Properties, and Applications	260
5.16.8.2 Extrusion of Copper-Nickel Alloys	261
5.16.9Extrusion of Copper-Nickel-Zinc Alloys (Nickel-Silver)	261
5.16.9.1 Material, Structure, Properties, and Applications	261
5.16.9.2 Extrusion of Nickel-Silver Alloys	262
5.16.9.3 Competition from Wire Casting.....	263
Extrusion of Semifinished Products in Titanium Alloys	263
5.17Materials, Their Properties, and Applications	263
5.17.1 The Structure and Its Influence on the Properties	263
5.17.2 The Most Important Titanium Alloys and Applications	264
5.17.3 Titanium Alloys Produced by Powder Metallurgy	266
5.18Billet Production, Extrusion	266
5.18.1 Casting, Billet Preparation, Billet Heating	266
5.18.2 Extrusion, Lubrication	266
5.18.3 Flow Stress, Extrusion Defects	267
5.19Tooling, Further Processing	268
Extrusion of Semifinished Products in Zirconium Alloys	268
5.20 Materials, Properties, and Applications	268
5.21 Billet Production, Extrusion.....	268
5.21.1 Casting, Billet Preparation	268
5.21.2 Extrusion, Influence of the Structure	268
5.22Tooling, Further Processing	269
Extrusion of Iron-Alloy Semifinished Products	269
5.23General	269
5.23.1 Process Basics	269
5.23.2 Importance of Steel Extrusion Today	270
5.24Mild-Steel Tubes	270
5.24.1 Use of Mechanical Presses.....	270
5.24.2 Application of Mechanical Presses	270
5.24.3 Dimensional Range and Throughput	271
5.25Seamless Alloy Steel Tubes	271
5.25.1 Extrusion in Competition with Other Hot-Working Processes	271
5.25.2 Alloys and Extrusion Properties.....	271
5.25.2.1 Alloy Groups, Structure, Properties, and Applications	271
5.25.2.2 Extrusion Properties, Defects	273
5.25.3Billet Production	274
5.25.3.1 Melting, Casting, Hot Working	274
5.25.3.2 Homogenizing, Billet Preparation	275
5.25.4Billet Heating, Lubrication.....	275
5.25.4.1 Billet Heating	275
5.25.4.2 Lubrication 276	
5.25.5 Extrusion Process.....	277
5.25.6 Tooling 278	
5.25.7 Further Processing, Testing	278

5.25.7.1 Further Processing	278
5.25.7.2 Testing	278
5.26Steel Sections	278
5.26.1 General	278
5.26.1.1 Extrusion Process, Materials	278
5.26.1.2 Competition with Other Deformation Processes	278
5.26.2 Materials, Starting Material, Process	279
5.26.3 Billet Production, Extrusion, Further Processing	280
5.26.3.1 Billet Preparation, Heating, Lubrication	280
5.26.3.2 Further Processing	280
5.26.4Tooling	281
Extrusion of Semifinished Products in Nickel Alloys (Including Superalloys)	281
5.27 General.....	281
5.28 Materials, Properties, and Applications	281
5.29 Billet Production	282
5.30 Billet Heating	282
5.31 Extrusion	283
5.31.1 Billet Preparation, Lubrication	283
5.31.2 Deformation Behavior and Extrusion Data.....	283
5.31.3 Defects and Their Prevention	286
5.32Tooling, Further Processing	286
Extrusion of Semifinished Products in Exotic Alloys	286
5.33Beryllium	287
5.33.1 Properties and Applications	287
5.33.2 Billet Production.....	287
5.33.3 Deformation Behavior, Extrusion	287
5.34Uranium	287
5.34.1 Properties, Applications	287
5.34.2 Deformation Behavior, Extrusion	288
5.35Molybdenum, Tungsten	288
5.35.1 Molybdenum.....	288
5.35.2 Tungsten	288
5.36Niobium and Tantalum	289
5.36.1 Tantalum	289
Extrusion of Powder Metals	289
5.37General	289
5.37.1 Main Application Areas of Powder Metallurgy.....	290
5.37.2 Advantages of Metal Powder Extrusion	290
5.37.3 Powder Production	290
5.37.4 Spray Compaction.....	290
5.38Powder Extrusion Processes	291
5.38.1 General	291
5.38.2 Shaking of Loose Powder into a Vertical, Heated Container and Direct Extrusion (Version a)	292
5.38.3 Precompaction of the Powder outside the Press	292
5.38.4 Encapsulation of the Powder before Extrusion (Version c).....	292
5.39 Mechanism and Flow Behavior in the Extrusion of Metal Powders	293
5.40 Load Variation	294
5.41 Examples of Powder Extrusion	294
5.41.1 Aluminum Alloys	294
5.41.2 Copper and Noble Metal-Base Alloys	296
5.41.3 Titanium Alloys	296
5.41.4 Iron Alloys	296
5.41.5 Nickel and Cobalt-Base High-Temperature Alloys	297
5.41.6 Exotic Materials.....	298

Extrusion of Semifinished Products from Metallic Composite Materials	298
5.42 Terminology and Examples	299
5.43 Flow Behavior in the Extrusion of Fiber Composite Materials	300
5.43.1 Criterion for Homogeneous Deformation.....	301
5.43.2 Deformation with Failure of the Composite Material	302
5.44 Production of Metallic Composite Materials	302
5.45 Application Examples	307
5.45.1 Simple Structures and Coatings	308
5.45.2 Metallic Fiber Composite Materials with Complex Structures	308
5.45.3 Metallic Fiber Composite Materials with P/M Structures	310
Chapter 6 Machinery and Equipment for Direct and Indirect Hot Extrusion	323
6.1Machinery and Equipment for Direct and Indirect Hot Extrusion	323
6.1.1Machinery for Direct Extrusion	323
6.1.1.1 Extrusion Press Design Principles	324
6.1.1.2 Main Subassemblies of the Direct-Extrusion Press	327
6.1.1.3 Auxiliary Equipment for Direct Extrusion	335
6.1.1.4 Hydraulic Drive and Control Systems for Direct Extrusion	338
6.1.1.5 Electrical Drive, Control, and Regulation for Direct Extrusion	341
6.1.1.6 Typical Operating Sequence for Direct Extrusion	344
6.1.2Machines for Indirect Extrusion	344
6.1.2.1 Press Design	345
6.1.2.2 Main Structural Components of Indirect-Extrusion Presses	347
6.1.2.3 Auxiliary Equipment for Indirect Extrusion	347
6.1.2.4 Hydraulic Drive Systems and Control for Indirect Extrusion	352
6.1.2.5 Electric Drive and Control for Indirect Extrusion	352
6.1.2.6 Typical Operating Sequence in Indirect Extrusion	353
6.2Presses and Plant for Tube Extrusion	353
6.2.1Direct Tube Extrusion	355
6.2.1.1 Machine Construction Details of Tube Extrusion Presses.....	355
6.2.1.2 Main Subassemblies and Modules of Direct Tube Extrusion Presses	357
6.2.1.3 Auxiliary Equipment for Direct Extrusion	361
6.2.1.4 Hydraulic Control Systems	361
6.2.1.5 Electrical Drive, Controls, and Additional Equipment for Direct Tube Extrusion	361
6.2.1.6Typical Operating Sequence for Direct Tube Extrusion	362
6.2.2Indirect Tube Extrusion	362
6.2.2.1 Machine Design Details	362
6.2.2.2 Main Subassemblies of Indirect Tube Extrusion Presses	364
6.2.2.3 Typical Operating Sequence for Indirect Tube Extrusion	365
Billet Heating Systems	365
6.3Induction Furnaces	365
6.3.1General	365
6.3.1.1 Single-Billet Furnace	366
6.3.1.2 Multibillet Furnaces	367
6.3.1.3 Induction Furnace with a Heated Holding Chamber	369
6.3.1.4 Boost Heating	370
6.3.1.5 Induction Furnaces with Hot Log Shear	372
6.3.2Gas-Fired Billet Preheat Furnace	372
6.3.2.1 General	372
6.3.2.2 Rapid-Heating Gas-Fired Preheat Furnace with Billet Preheating	373
6.3.2.3 Combination Induction Furnace and Rapid-Heating Gas-Fired Furnace	373
6.3.2.4 Rapid-Heating Gas-Fired Furnace with Boost Heater	374
6.3.2.5 Rapid-Heating Gas-Fired Furnace with Hot Log Shear.....	375
6.3.3Temperature Measurement and Control	375

6.3.4 Economics	375
6.3.5 Extrusion Billet Transport Mechanisms	375
Handling System.....	377
6.4 Handling Gear for Aluminum Alloy Products	378
6.5 Handling System for Copper Alloy Products	383
6.5.1 Wire Lines: Brass Wire Transport with Protective Baskets	383
6.5.2 Wire Line: Brass Wire Transport without Protective Baskets	383
6.5.3 Wire Line: Copper Wire Transport without Protective Baskets, Cooling under Water.....	384
6.5.4 Straight Line: Brass Transport for Rod, Tube, and Section	384
6.5.5 Straight-Line: Copper Tube and Section	385
6.6Extrusion Cooling Systems	385
6.6.1 Nitrogen Cooling	386
6.6.2 Water Cooling	386
6.6.3 Air Cooling	387
Age-Hardening Ovens for Aluminum Alloys	388
6.7Heat Transfer by Convection	388
6.7.1 Methods of Air Circulation	389
6.7.2 Fans	390
6.8 Design of the Chamber Furnace	390
6.9 Heating	391
6.10Transport Mechanisms.....	391
Equipment for the Production of Extrusion Billets	391
6.11Equipment for the Production of Aluminum Billets	391
6.11.1 Design and Configuration of Modern Continuous Casting Plants	391
6.11.2 Melting and Casting Furnaces	392
6.11.3 Processes for Melt Refining	394
6.11.4 Mold Casting Systems	397
6.11.5 Casting Plants	399
6.11.6 Homogenization Plants	400
Equipment for the Production of Copper Billets.....	400
6.12Plants with Furnace-Independent Molds	401
6.12.1 Melting and Casting Furnaces	402
6.12.2 Melt Feed to the Mold	402
6.12.3 Molds	403
6.12.3.1 Special Mold Designs	404
6.12.4 Protective Cover	404
6.12.5 Cooling and Control	404
6.13Plants with Furnace-Dependent Molds.....	404
6.13.1 Stimulus for the Development	404
6.13.2 Asarco System.....	405
6.13.3 Horizontal Casting Plants	405
6.13.4 Continuous Casting of Steel and Other Materials	405
Process Control in Direct and Indirect Hot Extrusion of Aluminum Alloys without Lubrication	406
6.14Process Control in Direct Hot Extrusion of Aluminum Alloys without Lubrication	406
6.14.1 Influence of the Friction between the Billet and the Container as well as the Deformation in the Deformation Zone on the Temperature of the Extruded Material as It Enters the Die Aperture.....	407
6.14.2 Heat Transfer in the Die Area	407
6.14.3 Measurement of the Extrusion Temperatures	407
6.14.4 Methods of Achieving Constant Exit Temperatures over the Length of the Extrusion or Ram Displacement in the Direct Hot Extrusion of Aluminum Alloys	408

6.15Process Control in Indirect Hot Extrusion of Aluminum Alloys without Lubrication	409
Process Control Concepts for Extrusion Plants	410
6.16Electrical-Electronic Control	410
6.16.1 Factors that Influence the Productivity and Quality of the Products in the Extrusion Process	412
6.16.2 Improvement in the Productivity and Product Quality by the Optimization of the Extrusion Process	412
Chapter 7 Extrusion Tooling	417
7.1Requirements of Tooling and Tooling Material	417
7.1.1 Requirements of the Extrusion Tooling	417
7.1.2 Requirements of the Tooling Materials	418
7.2Design of Tool Sets for Direct and Indirect Extrusion	419
7.2.1 Design of the Tool Set for Direct Extrusion	419
7.2.2 Design of the Tool Set for Indirect Extrusion	423
7.2.3 Sealing of the Shape-Producing Tooling with the Container	424
7.3Extrusion Tooling for Direct External and Internal Shape Production	427
7.3.1Control of Material Flow in the Shape-Forming Region of Extrusion Tooling	432
7.3.1.1Control of Material Flow in the Shape-Producing Regions in the Extrusion of Materials with Working Temperatures from 0 to 300 °C	435
7.3.1.2Control of Material Flow in the Shape-Producing Regions in the Extrusion of Materials with Working Temperatures from 300 to 600 °C	436
7.3.1.3Control of Material Flow in the Shape-Producing Regions in the Extrusion of Materials with Working Temperatures from 600 to 1300 °C ...	441
7.3.2 Dimensions of the Die Apertures in Relation to the Specified Section Dimensions at Room Temperature	441
7.3.3 Tooling for the Extrusion of Materials with Deformation Temperatures in the Range of 0 to 300 °C	445
7.3.4Tooling for the Extrusion of Materials with Deformation Temperatures in the Range of 300 to 600 °C.....	446
7.3.4.1 Tooling for the Extrusion of Magnesium Alloys	446
7.3.4.2 Tooling for the Extrusion of Aluminum Alloys	446
7.3.4.3 Manufacture and Operation of Aluminum Extrusion Tooling	455
Tools for the Extrusion of Materials with Deformation Temperatures of 600 to 1300°C	460
7.4Tools for Copper Alloy Extrusion	460
7.4.1 Construction of the Tool Set for Direct and Indirect Extrusion	461
7.4.2 Extrusion Dies and Mandrels for the Production of Tubes	462
7.4.2.1Extrusion Dies for the Production of Solid Sections in Copper-Zinc Alloys	464
7.4.2.2Extrusion Dies for the Extrusion of Solid Sections in Copper and Low-Alloyed Copper Alloys	465
7.4.2.3 Dies, Mandrels, and Bridge Dies for the Production of Hollow Sections	466
7.4.2.4 Extrusion Dies for the Production of Rod and Wire	467
7.4.3Manufacture and Use of Copper Extrusion Dies	468
7.4.3.1 Manufacture of the Extrusion Dies	468
7.4.3.2 Use of the Extrusion Tools	469
7.4.4Tooling for the Glass-Lubricated Extrusion of Titanium, Nickel, and Iron Alloys	470
7.4.4.1 Design of the Tool Set for Direct Extrusion	471
7.4.4.2 Tooling for the Extrusion of Titanium Alloys	471
7.4.4.3 Tooling for the Extrusion of Nickel Alloys	471
7.4.4.4 Tooling for Extrusion of Iron Alloys	472
7.5Extrusion Tools for Indirect Shape Production, Auxiliary, and Support Tooling	473
7.5.1 Mandrel Holder and Mandrel Cooling	477

7.5.2 Dummy and Cleaning Blocks for Round and Oval (Rectangular Billet) Containers	478
7.5.2.1 Dummy and Cleaning Blocks for Direct Extrusion	478
7.5.2.2 Dummy and Cleaning Blocks for Indirect Extrusion	480
7.5.3 Extrusion Stems for Round and Oval Billet Containers.....	481
7.5.3.1 Extrusion Stems for Direct Extrusion	482
7.5.3.2 Extrusion Stems for Indirect Extrusion	483
7.5.3.3 Calculations and Dimensions for Extrusion Stems.....	483
7.5.3.4 Examples of Stem Calculations for Direct and Indirect Extrusion	485
7.5.3.5 Thermomechanical Stressing of Stems during Extrusion	488
7.5.4 Temperature-Related Maintenance and Handling of Extrusion Tooling	488
7.5.5 Containers	489
7.5.5.1 Container Construction.....	489
7.5.5.2 Thermomechanical Stressing of the Container during Extrusion	495
7.5.5.3 Container Heating and Cooling	496
Recent Developments in Resistance Heating of Containers	500
7.6 Induction Heating for Containers	500
7.6.1 Combined Container Heating and Cooling System	501
7.7 Design, Calculation, and Dimensioning of Containers	502
Static- and Elastic-Based Analysis and Dimensioning of Containers Loaded in Three Dimensions	508
7.8 Design of a Single-Piece Container Loaded in Three Dimensions	509
7.9 Design of a Two-Part Container.....	510
7.9.1 Calculation of the Prestresses σ_r^x and σ_t^x Developed in a Two-Part Container by the Interference-Fit Forces	510
7.9.1.1 Calculation of the Working Stresses σ_r^{xx} and σ_t^{xx} from the Extrusion Forces in a Two-Part Container.....	510
7.9.1.2 Determining the Operating Stresses σ_r^{xxx} and σ_t^{xxx} by Addition (Additive Superimposition) of σ_r^x and σ_t^x and σ_r^{xx} and σ_t^{xx} in a Two-Part Container	510
7.9.1.3 Calculation of the Equivalent Stress σ_v in a Two-Part Container	511
7.9.2 Design of a Three-Part Container	511
7.9.2.1 Calculation of the Prestresses σ_r^x and σ_t^x Developed by the Interference-Fit Forces in a Three-Part Container	511
7.9.2.2 Calculation of the Working Stresses σ_r^{xx} and σ_t^{xx} Resulting from Deformation Forces during Extrusion in a Three-Part Container	512
Calculation of the Working Stresses σ_r^{xxx} and σ_t^{xxx} by the Addition of the Prestresses σ_r^x and σ_t^x and σ_r^0 and σ_t^0 and the Operating Stresses σ_r^x and σ_t^x (Additive Superimposition) in the Three-Part Container	512
7.9.2.4 Calculation of the Equivalent Stresses, σ_v , in the Three-Part Container	513
7.10 Examples of Calculations for Different Containers, Their Stresses and Dimensions	513
7.10.1 Design of a Two-Part Container with a Round Bore for Aluminum Alloys	513
7.10.1.1 Two-Part Container for a 25 MN Extrusion Press	514
7.10.2 Calculation of a Three-Part Container with an Oval Bore for Aluminum Alloys	514
7.10.2.1 Three-Part Container for a 25 MN Extrusion Press	515
7.10.3 Calculation of a Three-Part Container with a Round Bore for Copper Alloys ..	515
7.10.3.1 Three-Part Container for a 25 MN Extrusion Press.....	515
7.10.4 Influence of Axial Loading of the Container	516
7.10.5 Operating Conditions from Elastic/Plastic Behavior of the Tool Material under the Influence of the Thermomechanical Working Stresses	517
7.11 Manufacture of Containers	519
7.12 Container Operation	520
7.13 Maintenance of Containers	521

Hot Working Materials for the Manufacture of Extrusion Tooling	522
7.14 Hot Working Steels	523
7.14.1 Classic Hot Working Steels.....	523
7.14.1.1 Hardening and Tempering of the Classic Hot Working Steels	533
7.14.1.2 Machining of Hardened and Tempered Hot Working Steels	534
7.14.1.3 Surface Heat Treatment of Extrusion Tools in Classic Hot Working Steels	535
7.14.2 Austenitic Hot Working Steels.....	536
7.14.3 Classification of Hot Working Steels	538
7.15 Special Materials	539
7.15.1 Cobalt Alloys	539
7.15.2 Molybdenum Alloys	540
7.15.3 Nickel Alloys	540
7.15.4 Metal-Ceramic Composite Materials.....	541
7.15.5 Hard Metals	542
7.15.6 Pure Ceramic Hot Working Materials	542
7.16 Further Developments	542
7.17 Hot Working Materials for Different Extruded Materials for the Manufacture of Extrusion Tooling for Direct and Indirect Forming.....	543
Chapter 8 Quality Management in Extrusion.....	551
8.1 Quality	551
8.2 Quality Management	551
8.2.1 Quality Management System	551
8.2.2 Introduction of a QMS	552
8.2.3 Process Chain.....	553
8.2.4 Product Liability	555
8.2.5 Economics	556
8.3 Quality Control.....	556
8.3.1 Organization	556
8.3.1.1 Process Organization	557
8.3.2 Responsibilities	558
8.3.2.1 General Requirements	558
8.3.3 Audits	558
QMS Audit	559
8.3.3.1 Environmental System Audit	560
8.3.3.2 Process Audit	560
8.3.3.3 Product Audit	560
8.3.3.4 Inspector Audit	561
8.3.4 Testing	561
8.3.4.1 Failure Modes and Effect Analysis	561
8.3.4.2 Inspection Planning	561
8.4 Outlook	563
Appendix A List of Formula Symbols.....	565
Appendix B Approximate Composition of Materials	567
Index.....	579